

# User manual for Universal Water-Resistant Wireless Headset K10C



## Specifications:

- Bluetooth version: v4.1
- Max. battery life: 8h
- Charging time: around 2h
- Resistance certification: IPX5
- Charging interface: MicroUSB



- 1) Power On/Off
- 2) Volume+
- 3) Volume-
- 4) Mute button
- 5) MicroUSB charging port

- 6) Speaker
- 7) Multifunction button
- 8) 180 degrees rotation
- 9) 200 degrees rotation
- 10) Double microphone

## **Connecting the headset to the smartphone**

Turn on the headset and hold the multifunction button for about 5 seconds until the indicator starts to flash red and blue. Enable Bluetooth on your phone and search for the headset. When found, tap to connect it and type a password if needed. The default password is 0000.

To connect the headset with two phones, power on the headset and hold the multifunction button for about 5 seconds until the indicator starts to flash red and blue. Enable the Bluetooth on the first phone and pair as described above. Turn off the Bluetooth on the first phone and repeat the connecting procedure with the second phone. When done, turn on the Bluetooth on the first phone and connect it to the headset.

Your headset will try to reconnect the lost connection by itself. If it doesn't try to reconnect by itself, then click the multifunction button once or connect the phone manually.

### **LED light**

- Red when charging
- Blue when charged
- Flashing red with voice prompt when the battery is low